

A new version of software (v3.02) for the APS has been released.

This release corrects a number of bugs - some new, some not so new.

Bug Fixes

- Channels controlled by DMX turned on but couldn't be turned off.
- Further fixes to RDM messages.
- The touch screen may have locked up randomly and very rarely.
- The lock on an SD card was ignored (V2.0+)
- Export of files didn't work (V3.0+)
- Inserting or removing an SD card in the Import/Export menu would cause the outputs to glitch (V3.0+)
- Infinite loss time wasn't. It would take many hours but it would time out.
- The stagger start-up was irregular when very low Stagger times were used.
- When entering some values, no limit was set and with sufficient numbers it could cause the system to restart.
- If there was no high limit set on a phase, it was possible to set an invalid low limit.
- Setting DMX hold time could sometimes add extra seconds.

LSC recommends that all users download and install this software update.

The new version can be downloaded from [here](#) .

An SD card is required to install this software.

